INTRODUCTION

This publication provides a historical summary of the changes made to the application firmware and hardware of the BE1-700V Digital Protective Relay.

Revision history information for BESTCOMS*Plus*® software is provided in the *BESTCOMSPlus Software Revision History* document.

This information is provided for confidential use with the mutual understanding that it will not be used in any manner detrimental to the interests of Basler Electric.

FIRMWARE REVISION HISTORY

The revision history for BE1-700V application firmware is provided as follows. Revisions are presented in reverse chronological order.

Firmware Version and Date	Change
4.00.05, Aug-24	• Corrected error result from specific HMI navigation sequence
4.00.04, Jul-24	• Improved IRIG signal detection
4.00.03, Apr-24	• Initial release

HARDWARE REVISION HISTORY

The revision history for BE1-700V hardware is provided as follows. Revisions are presented in reverse chronological order.

Hardware Version and Date	Change
AU, Aug-24	• Added CE and UKCA labels
AT, Apr-24	• Initial release of version 4 firmware

For terms of service relating to this product and software, see the *Commercial Terms of Products and Services* document available at www.basler.com/terms.